09,966,316.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,762,122 B2

DATED

: July 13, 2004

INVENTOR(S) : Mis et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11,

Line 15, should read -- first barrier layer comprising nickel on the first under --Line 24, should read -- and a gold layer on the second barrier layer comprising --

Colum 12,

Line 31, should read -- input/output pad, and a gold layer on the second barrier --

Signed and Sealed this

Page 1 of 1

Seventh Day of December, 2004

JON W. DUDAS Director of the United States Patent and Trademark Office